
Quick Installation Guide



Three-Phase EPS Box

1. Introduction


Three-phase EPS Box integrates two contactors which provide power steering for users. It is compatible with Three-phase EPS change-over application. Configured with Three-phase EPS Box, customers need to connect 13 wires to complete the steering circuit. It can simplify the operation and improve security.



2. Overview







111			
— Ĭ	Object	Description	
	1	EPS	
H	2	Grid	
	3	Load	

3. Preparation

3.1Packing List Checking

Before installation, make sure that nothing inside the package is damaged. The following items should be inside the package.







Silicone sleeves

X4 X 4

self-tapping

screws X 4

terminals X15

X15

3.2 Tools

Before you start, get the following tools ready.


















4. Mounting

Step 1:


Make sure the installation site does not expose to direct sunlight. Then install the four cushion blocks on Three-phase EPS Box with self-tapping screws.



self-tapping screws


Step 2:

Use Three-phase EPS Box with cushion blocks as a template to mark the four holes' position on the wall with marker pen.



Step 3:

Drill holes with $\Phi 6$ driller carefully, make sure the holes are deep enough for installing. Install the expansion tubes through cushion blocks into the holes and tighten them.







-Tighten the expansion tubes

Step 4:

Install the expansion screws with screwdriver to fix the Three-phase EPS Box.





5. Wiring Connection

5.1 Wires making

① Prepare wires as below. Use the diagonal plier to trip :② Insert wire into cable gland, then insert the 15mm of insulation from side of the wire.





end of wire into cold pressed terminal and tighten it.






If AWG-10 wires are used, please pass the wires through the silicone sleeves to aviod leakage at the insertions.

5.2 Grid-Wires Connection

Use the manual wrench to screw off the cap on cable nut, then insert Grid-L wires and Grid-N wires into the ports (L1,L2,L3,L4) of contactor A through the cable nut and tighten them with screwdriver.







Top View


Left View




Please prevent other wires from getting loose during operation.

5.3 EPS-Wires Connection

Screw off the cap on cable nut, then insert EPS-L wires and EPS-N wires into ports (L1,L2,L3,L4) of contactor B through the cable nut and tighten them with screwdriver.






Left View



5.4 Load-Wires Connection


Screw off the cap on cable nut, then insert Load-L wires and Load-N wires into ports (T1, T2, T3, T4) of contactor C through the cable nut and tighten them with screwdriver.






5.5 Earth-Wire Connection


In EU, insert GND wire into port of contactor (B: L4) through the cable nut and tighten it with screwdriver. In AU, insert N wire into ports of contactor(A: L4&B: L4).








5.6 Checking

Please make sure all wires are tightened. Wire connection in Three-phase EPS-Box.









For EU

For AU

6. Technical Parameters

Grid	
Max.AC input current (A)	3x63
Rated AC voltage (V)	3/N/PE~400/230
Rated AC frequency (Hz)	50/60
EPS	
Max.EPS input current (A)	3x63
Rated EPS voltage (V)	3/N/PE~400/230
Rated EPS frequency (Hz)	50/60

Load			
Rated output current(A), on grid mode	3x63*		
Rated output current(A), EPS mode	3x63*		
Rated Grid Voltage(V)	3/N/PE~400/230		
Rated Grid Frequency(Hz)	50/60		
Genaral Data			
Operating Temperature range ($^{\circ}$ C)	-20~+60		
Dimension (mm)	300x220x170		
Weight (kg)	4.85		



*: The output current will be reduced when the operating temperature exceeds 40°C. At 50°C, the output current drops to 95%. At 60°C, it drops to 80%.

614.00213.03